

SECRET

OUT57332

S E C R E T 082309Z

1965 DEC 8 23 21Z

25X1

1. CAMERA B 23 WAS USED IN MISSION 8060 FLOWN ON 7 DECEMBER 1965. PROCESSING WAS ACCOMPLISHED BY BARKSDALE.

2. ORIGINAL NEGATIVE:

A. THE EXPOSURE WAS ADEQUATE AND THE RESOLUTION IS GOOD WHERE NOT DEGRADED BY WEATHER AND/OR VEHICLE TURN MANEUVERS.

B. 9R SIDE: INBOARD AND OUTBOARD ROLLER CHATTER (PRESSURE ROLLER STATIC) AND SLIGHT EDGE FOG ALONG BOTH FILM EDGES ARE PRESENT THROUGHOUT THE MISSION. A MANUFACTURER'S SPLICE IS LOCATED IN FRAME 1173 WITH ASSOCIATED SMALL EMULSION LIFTS IN FRAME 1175.

C. 9L SIDE: EDGE STATIC IS PRESENT ALONG THE INBOARD AND OUTBOARD EDGES. ROLLER CHATTER APPEARS ON BOTH EDGES OF THE FILM BUT IS MORE PRONOUNCED ON THE INBOARD EDGE. IN THE FIRST 600 FRAMES OF THE MISSION THERE ARE SEVERAL ROWS OF MINUS DENSITY DOTS THAT ARE ALL APPROXIMATELY 1.7" APART. HEAT SPLICES ARE BETWEEN FRAMES 914/915 1598/1599 AND 1599/1600. MANUFACTURING SPLICES ARE LOCATED IN FRAMES 1189 AND 2118. BOTH OF THESE SPLICES ARE ACCOMPANIED BY THE NORMAL FOG AND STATIC.

D. BOTH SIDES: THE FIRST TITLED FRAME IS 0000 AND THE LAST TITLED FRAME IS 2259.

E. THERE WERE NO MAJOR PROCESSING ANOMALIES OR CAMERA MALFUNCTIONS IN THIS MISSION.

3. POSITIVE:

09 DEC 1965

DISTRIBUTION

No.	Office	Action
12	FIN	
	CS	
	ADMIN	
	SEC BR	
	P & DS	
	CSD	
	IPD	
	PD	
	PSD	
	PSD-ICS	
34	TID	✓
	IAD	
	PAG	
	DIAXX-4	
	SPAD	
	NSA-LO	
	DIA-AP	

Advance copy
Sanitized

Declassification Review by NGA/DoD

SECRET

-2-

RECEIVED SUITABILITY IS POOR DUE TO A LARGE AMOUNT OF CLOUD COVER.

B. PRINTING AND PROCESSING WERE GOOD.

C. CLOUDS DEGRADE OR OBSCURE APPROXIMATELY 85 PERCENT OF THIS MISSION.

S E C R E T

--END OF MESSAGE--

1